

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	11-Aug-08
Time	10:59 AM
Monitoring Location	Hong Hoi Chee Hong Temple (I-2)
Parameter	Suspended Solid
Action & Limit Levels	7.68 / 8.34
Measured Level	1.8 (higher than 120% of control control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 1.45 is recorded at Control Station (I-2-C)
Actions taken / to be taken	The measured SS levels at both impact & control stations were well below the Action Level of baseline measurement and no direct disturbance was observed contributed by project construction activities (levelling of piling platform). There is no evidence to show the exceedance is project-related and no action is considered necessary.
Remarks	The action level exceedance is considered not to be project-related.

Prepared by: Antony Wong

Designation: Environmental Team Leader

Signature:



Date: 20-Aug-08

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	13-Aug-08
Time	10:50 AM
Monitoring Location	Hong Hoi Chee Hong Temple (I-2)
Parameter	Suspended Solid
Action & Limit Levels	7.68 / 8.34
Measured Level	0.8(higher than 130% of control control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 0.2 is recorded at Control Station (I-2-C)
Actions taken / to be taken	No action is required as the monitoring result was well below both Action & Limit Levels and no direct disturbance was observed contributed by project construction activities (levelling of piling platform). There is no evidence to show the exceedance is project-related
Remarks	The limit level exceedance is considered not project-related.

Prepared by: Antony Wong

Designation: Environmental Team Leader

Signature:



Date: 25-Aug-08

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	13-Aug-08
Time	11:58 AM
Monitoring Location	Squatters (I-3)
Parameter	Suspended Solid
Action & Limit Levels	6.13 / 7.23
Measured Level	0.25(higher than 130% of control control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 0.15 is recorded at Control Station (I-3-C)
Actions taken / to be taken	No action is required as the monitoring result was well below both Action & Limit Levels and no direct disturbance was observed contributed by project construction activities (site tidying & cleaning and removal of dead trees). There is no evidence to show the exceedance is project-related
Remarks	The limit level exceedance is considered not project-related.

Prepared by: Antony Wong

Designation: Environmental Team Leader

Signature:



Date: 25-Aug-08