

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	01-Sep-08
Time	9:02am
Monitoring Location	Sik Sik Yuen Ho Fung College (I-1)
Parameter	Suspended Solid
Action & Limit Levels	8.85 / 10.17
Measured Level	3.9 (higher than 130% of control control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 2.8 is recorded at Control Station (I-1-C)
Actions taken / to be taken	No action is required as the monitoring result was well below both Action & Limit Levels and no direct disturbance was observed contributed by project construction activities (tree transplant, soil nail & mobilization of constructional plants). There is no evidence to show the exceedance is project-related. No exceedance was recorded for measurement performed on 3/9/2008.
Remarks	The limit level exceedance is considered not project-related.

Prepared by: Desmond Chan

Designation: Senior Environmental Consultant

Signature:



Date: 11-Sep-08

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	05-Sep-08
Time	9:07am
Monitoring Location	Sik Sik Yuen Ho Fung College (I-1)
Parameter	Turbidity
Action & Limit Levels	9.75 / 12.47
Measured Level	18.95
Possible reason for Action or Limit Level Non-compliance	Muddy water was observed generated from other CEDD's project (Yick Hing) at upper stream regarding to site investigation. Refer to attached photos for details
Actions taken / to be taken	No action is required as the result of monitoring station was below the control station and no direct disturbance was observed contributed by the project construction activities.
Remarks	The limit level exceedance is considered not to be project-related.

Prepared by: Desmond Chan

Designation: Environmental Consultant

Signature:



Date: 08-Sep-08

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	05-Sep-08
Time	10:55am
Monitoring Location	Hong Hoi Chee Hong Temple (I-2)
Parameter	Suspended Solid
Action & Limit Levels	7.68 / 8.34
Measured Level	4.9 (higher than 130% of control control station's SS)
Possible reason for Action or Limit Level Non-compliance	No construction work except mobilization of geological investigation plant was observed on site during measurement. Exceedance may be possibly caused by air pipe leakage of air compressor from other project (GE/2006/17) regarding site inspection on 5 September 2008. (see attached photo)
Actions taken / to be taken	The Contractor is requested to contact the Contractor of Project GE/2006/17 to fix the air pipe as soon as possible. No exceedance was recorded for measurement performed on 8/9/2008.
Remarks	The limit level exceedance is considered not project-related.

Prepared by: Desmond Chan

Designation: Senior Environmental Consultant

Signature:



Date: 16-Sep-08

Interim Notifications of Environmental Quality Limits Exceedances


Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	05-Sep-08
Time	10:55am
Monitoring Location	Sik Sik Yuen Ho Fung College (I-1)
Parameter	Suspended Solid
Action & Limit Levels	8.85 / 10.17
Measured Level	22.6
Possible reason for Action or Limit Level Non-compliance	Muddy water was observed generated from CEDD's project (Yick Hing) at upper stream regarding to site investigation. Refer to attached photos for details
Actions taken / to be taken	No action is taken as the result of monitoring station was below the control station and no direct disturbance was observed contributed by the project construction activities.
Remarks	The limit level exceedance is considered not to be project-related.

Prepared by: Desmond Chan

Designation: Senior Environmental Consultant

Signature:



Date: 16-Sep-08

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	5-Sep-08
Time	10:55am
Monitoring Location	Sik Sik Yuen Ho Fung College (I-1)
Parameter	Suspended Solid
Action & Limit Levels	8.85 / 10.17
Measured Level	22.6
Possible reason for Action or Limit Level Non-compliance	No construction work of this project was undertaken during measurement. Muddy runoff was observed from another CEDD's construction site and the runoff discharged to the upstream of the impact monitoring station I-1.
Actions taken / to be taken	No action was considered to be necessary as exceedance was likely to be caused by the mentioned runoff, the SS exceedance is unlikely to be project-related.
Remarks	The limit level exceedance is considered not to be project-related.

Prepared by: Desmond Chan

Designation: Senior Environmental Consultant

Signature:



Date: 9/16/2008 (revised on 15 October)

Photographic record for exceedance of Suspended Solid recorded at Sik Sik Yuen Ho Fung College (I-1) on 05-Sep-08



Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	25-Sep-08
Time	10:35 AM
Monitoring Location	Hong Hoi Chee Hong Temple (I-2)
Parameter	Suspended Solid
Action & Limit Levels	7.68 / 8.34
Measured Level	2.9 (higher than 130% of control control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 2.1 is recorded at Control Station (I-2-C)
Actions taken / to be taken	No action is taken as the monitoring result was well below both Action & Limit Levels and no direct disturbance was observed contributed by project construction activities (ground investigation). There is no evidence to show the exceedance is project-related. No exceedance was recorded for measurement performed on 27/9/2008.
Remarks	The control limit level exceedance is considered not project-related.

Prepared by: Desmond Chan

Designation: Senior Environmental Consultant

Signature:



Date: 08-Oct-08

Photographic record for exceedance of Suspended Solid recorded at Hong Hoi Chee Hong Temple (I-2) on 25-Sep-08

