

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	9-Jan-09
Time	10:20 AM
Monitoring Location	Hong Hoi Chee Hong Temple (I-2)
Parameter	Suspended Solid
Action & Limit Levels	7.68 / 8.34
Measured Level	5.2 (higher than 120% of control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 4.2 is recorded at Control Station (I-2-C)
Actions taken / to be taken	The measured SS level was below baseline Action / Limit Level and was within the range of baseline SS concentration (1-8.5mg/L). Site tidiness and cleanliness and drilling hole for air vent shaft construction were undertaken during the measurement and no direct disturbance was observed. Thus, the exceedance is considered to be contributed by natural variation and no action should be required.
Remarks	

Prepared by: Antony Wong

Designation: Environmental Team Leader

Signature:



Date: 19-Jan-09

Photographic record for exceedance of Suspended Solid recorded at Hong Hoi Chee Hong Temple (I-2) on 09-Jan-09



Photo taken at I-2



Photo taken at I-2-C

Interim Notifications of Environmental Quality Limits Exceedances

Incident Report on Action Level or Limit Level Non-compliance

Project	Tsuen Wan Drainage Tunnel
Date	9-Jan-09
Time	11:50 AM
Monitoring Location	Squatters (I-3)
Parameter	Suspended Solid
Action & Limit Levels	6.13 / 7.23
Measured Level	2.5 (higher than 120% of control station's SS)
Possible reason for Action or Limit Level Non-compliance	A low SS level of 2.0 is recorded at Control Station (I-3-C)
Actions taken / to be taken	The measured SS level was below baseline Action / Limit Level and was within the range of baseline SS concentration (1- 7.5mg/L). Site tidiness and cleanliness, drilling pre-bore H-pile and installation of H-pile and grout pre-bore H-pile were undertaken during the measurement and no direct disturbance was observed. Thus, the exceedance is considered to be contributed by natural variation and no action should be required.
Remarks	

Prepared by: Antony Wong

Designation: Environmental Team Leader

Signature:



Date: 19-Jan-09

Photographic record for exceedance of Suspended Solid recorded at Squatters (I-3) on 09-Jan-09



Photo taken at I-3



Photo taken at I-3-C